

ISO 18941:2017-07 (E)

Imaging materials - Colour reflection prints - Test method for ozone gas fading stability

| Contents | | Page |
|-----------------------|--|-------------|
| Foreword | | iv |
| Introduction | | v |
| 1 | Scope | 1 |
| 2 | Normative references | 1 |
| 3 | Terms and definitions | 1 |
| 4 | Requirements | 3 |
| 5 | Target selection | 3 |
| 6 | Measurements | 4 |
| 6.1 | Use of replicates and reference samples | 4 |
| 6.2 | Holding and measurement conditions | 4 |
| 6.3 | Measured attributes | 5 |
| 6.3.1 | Definition of density terms | 5 |
| 6.3.2 | Density attributes to be measured | 5 |
| 6.3.3 | Definitions of colorimetry terms | 6 |
| 6.3.4 | Colorimetry values to be measured | 6 |
| 7 | Calculations and computations | 6 |
| 7.1 | Computation of densitometric attributes | 6 |
| 7.2 | Density change in dmin patches | 6 |
| 7.3 | Percentage density change in primary colour patches | 6 |
| 7.4 | Percentage density change in secondary (mixed) colour patches | 6 |
| 7.5 | Percentage density change in composite neutral patch | 6 |
| 7.6 | Colour balance shift in composite neutral patch | 7 |
| 7.7 | Colour balance shift in secondary (mixed) colour patches | 7 |
| 7.8 | Colour balance in dmin patches by colorimetry | 7 |
| 7.9 | Effects of colorant fading and stain formation on colour photographs | 7 |
| 8 | Test methods -- Gas fading (ozone) | 7 |
| 8.1 | General | 7 |
| 8.2 | Apparatus | 8 |
| 8.3 | Test procedure | 15 |
| 9 | Test environment conditions | 16 |
| 9.1 | Humidity control calibration | 16 |
| 9.2 | Relative humidity | 16 |
| 9.3 | Temperature | 16 |
| 9.4 | Ozone concentration | 16 |
| 10 | Test report | 17 |
| 10.1 | General reporting requirements | 17 |
| 10.2 | Ozone test reporting | 17 |
| Annex A (informative) | Method for interpolation | 19 |

| | |
|---|-----------|
| Annex B (normative) Reciprocity considerations | 20 |
| Bibliography | 22 |