

ISO 10791-1:1998-09 (E)

Test conditions for machining centres - Part 1: Geometric tests for machines with horizontal spindle and with accessory heads (horizontal Z-axis)

Contents		Page
1	Scope	1
2	Normative references	2
3	Preliminary remarks	2
3.1	Measuring units	2
3.2	Reference to ISO 230-1	2
3.3	Testing sequence	2
3.4	Tests to be performed	2
3.5	Measuring instruments	2
3.6	Machining tests	3
3.7	Diagrams	3
3.8	Pallets	3
3.9	Software compensation	3
3.10	Machine configurations	3
3.11	Designation	3
3.12	Minimum tolerance	3
4	Geometric tests	6
4.1	Straightness of linear motions	6
4.2	Angular deviations of linear motions	9
4.3	Squareness between linear motions	12
4.4	Spindle	15
4.5	Table or pallet	20
4.6	Supplementary axes parallel to the Z-axis	28
Annex A (normative) Accessory 45° split indexable heads		32
Annex B (normative) Accessory swivel heads		41
Annex C (normative) Accessory 45° split continuous heads		48
Annex D (informative) Bibliography		55