

# ISO 230-1:1996-07 (E)

## Test code for machine tools - Part 1: Geometric accuracy of machines operating under no-load or finishing conditions

---

<b>Contents</b>		<b>Page</b>
<b>1</b>	<b>Scope</b> .....	<b>1</b>
<b>2</b>	<b>General considerations</b> .....	<b>1</b>
2.1	Definitions relating to geometric tests .....	1
2.2	Test methods and use of measuring instruments .....	1
2.3	Tolerances.....	2
2.31	Tolerances on measurements when testing machine tools .....	2
2.311	Units of measurement and measuring ranges .....	2
2.312	Rules concerning tolerances .....	2
2.32	Subdivisions of tolerances.....	2
2.321	Tolerances applicable to test pieces and to individual components of machine tools.....	2
2.321.1	Tolerances of dimension .....	2
2.321.2	Tolerances of form .....	3
2.321.3	Tolerances of Position .....	3
2.321.4	Influence of errors of form in determining positional errors.....	3
2.321.5	Local tolerances .....	3
2.322	Tolerances applicable to the displacement of a component of a machine tool .....	4
2.322.1	Tolerances of positioning.....	4
2.322.11	Tolerances of repeatability.....	4
2.322.2	Tolerances of the form of trajectory.....	4
2.322.3	Tolerances of relative position of straight-line motion .....	4
2.322.4	Local tolerance of displacement of a component.....	5
2.323	Overall or inclusive tolerances .....	5
2.324	Symbols and positions of tolerances for relative angular positions of axes, slideways, etc .....	5
2.325	Conventional definition of the axes and of the movements .....	5
<b>3</b>	<b>Preliminary Operations</b> .....	<b>5</b>
3.1	Installation of the machine before test .....	5
3.11	Levelling .....	5
3.2	Conditions of the machine before test.....	5
3.21	Dismantling of certain components .....	5
3.22	Temperature conditions of certain components before test .....	5
3.23	Functioning and loading.....	6
<b>4</b>	<b>Machining tests</b> .....	<b>6</b>
4.1	Testing .....	6
4.2	Checking of workpieces in machining tests .....	6
<b>5</b>	<b>Geometric tests</b> .....	<b>6</b>
5.1	General .....	6
5.2	Straightness.....	6
5.21	Straightness of a line in a plane or in space .....	7
5.211	Definition .....	7
5.211.1	Straightness of a line in a plane .....	7
5.211.2	Straightness of a line in space.....	7
5.212	Methods of measurement of straightness.....	7
5.212.1	Methods based on the measurement of length.....	7
5.212.11	Straightedge method(formerly 5.212.1) .....	8
5.212.111	Measurement in a vertical plane .....	8
5.212.112	Measurement in a horizontal plane .....	8
5.212.12	Taut-wire and microscope method(formerly 5.212.3).....	9

5.212.13	Alignment telescope method.....	10
5.212.14	Alignment laser technique.....	10
5.212.15	Laser interferometry technique.....	10
5.212.2	Methods based on the measurement of angles .....	11
5.212.21	Precision level method.....	11
5.212.22	Autocollimation method.....	12
5.212.23	Method by laser interferometer (angle measurement) .....	12
5.213	Tolerance.....	13
5.213.1	Definition .....	13
5.213.2	Determination of tolerance .....	13
5.22	Straightness of components .....	13
5.221	Definition .....	13
5.222	Methods of straightness measurement.....	13
5.222.1	Reference grooves or reference surface of tables.....	13
5.222.2	Slideways.....	14
5.222.21	Vee surfaces.....	14
5.222.22	Cylindrical surfaces.....	14
5.222.23	Single vertical surfaces.....	15
5.222.24	Slant-bed configuration .....	15
5.222.3	Tolerances.....	15
5.23	Straight-line motion.....	15
5.231	Definitions .....	15
5.231.1	Positional deviations.....	15
5.231.2	Linear deviations .....	15
5.231.3	Angular deviations .....	16
5.232	Methods of measurement.....	16
5.232.1	Methods of measurement of linear deviations .....	16
5.232.11	Method with a straightedge and a dial gauge (formerly 5.232.1).....	16
5.232.12	Method with microscope and taut wire (formerly 5.232.2) .....	16
5.232.13	Method using an alignment telescope .....	16
5.232.14	Method using a laser .....	16
5.232.15	Method using angle measurements .....	16
5.232.2	Methods of measurement of angular deviation.....	16
5.232.21	Method using a precision level .....	17
5.232.22	Method using an autocollimator .....	17
5.232.23	Method using a laser .....	17
5.233	Tolerance .....	17
5.233.1	Tolerance for the linear deviation of straight-line motion.....	17
5.233.2	Tolerance for the angular deviation of straight-line motion .....	17
5.3	Flatness .....	17
5.31	Definition .....	17
5.32	Methods of measurement .....	17
5.321	Measurement of flatness by means of a surface plate .....	17
5.321.1	Measurement by means of a surface plate and a dial gauge.....	17
5.322	Measurement of flatness by means of straightedge(s) .....	18
5.322.1	Measurement by means of a family of straight lines by displacement of a straightedge(formerly 5.322) .....	18
5.322.2	Measurement by means of straightedges, a precision level and a dial gauge .....	18
5.323	Measurement of flatness by means of a precision level .....	19
5.323.1	Measurement of a rectangular surface.....	19
5.323.2	Measurement of plane surfaces with circular contours .....	19
5.324	Measurement of flatness by optical methods.....	20
5.324.1	Measurement by an autocollimator .....	20
5.324.2	Measurement by a sweep optical Square .....	20
5.324.3	Measurement by an alignment laser.....	21
5.324.4	Measurement by a laser measuring system .....	21
5.325	Measurement by a coordinate measuring machine.....	22
5.33	Tolerances .....	22
5.4	Parallelism, equidistance and coincidence .....	22
5.41	Parallelism of lines and planes .....	22
5.411	Definitions .....	22
5.412	Methods of measurement .....	22

5.412.1	General, for axes .....	22
5.412.2	Parallelism of two planes .....	23
5.412.21	Straightedge and dial gauge .....	23
5.412.22	Precision level method .....	23
5.412.3	Parallelism of two axes .....	23
5.412.31	Plane passing through two axes .....	23
5.412.32	Second plane perpendicular to the first .....	23
5.412.4	Parallelism of an axis to a plane .....	24
5.412.5	Parallelism of an axis to the intersection of two planes .....	24
5.412.6	Parallelism of the intersection of two planes to a third plane .....	24
5.412.7	Parallelism between two straight lines, each formed by the intersection of two planes ....	25
5.413	Tolerances.....	25
5.42	Parallelism of motion .....	25
5.421	Definition .....	25
5.422	Methods of measurement.....	26
5.422.1	General .....	26
5.422.2	Parallelism between a trajectory and a plane.....	26
5.422.21	Plane is on the moving component itself .....	26
5.422.22	Plane is not on the moving component itself.....	26
5.422.3	Parallelism of a trajectory to an axis.....	26
5.422.4	Parallelism of a trajectory to the intersection of two planes .....	27
5.422.5	Parallelism between two trajectories .....	27
5.423	Tolerance.....	27
5.43	Equidistance .....	27
5.431	Definition .....	27
5.432	Methods of measurement.....	27
5.432.1	General .....	27
5.432.2	Special case of the equidistance of two axes from the plane of pivoting of one of the axes.....	27
5.433	Tolerance.....	28
5.44	Coaxiality, coincidence or alignment.....	28
5.441	Definition .....	28
5.442	Method of measurement.....	28
5.443	Tolerance.....	29
5.5	Squareness or perpendicularity .....	29
5.51	Squareness of straight lines and planes .....	29
5.511	Definition .....	29
5.512	Methods of measurement.....	29
5.512.1	General .....	29
5.512.2	Two planes at 90° to each other.....	30
5.512.3	Two axes at 90° to each other .....	30
5.512.31	The two axes are fixed axes .....	30
5.512.32	One of the axes is an axis of rotation .....	30
5.512.4	An axis and a plane at 90° to each other .....	30
5.512.41	Fixed axis .....	30
5.512.42	Axis of rotation .....	30
5.512.5	An axis at 90° to the intersection of two planes.....	30
5.512.51	Fixed axis .....	30
5.512.52	Axis of rotation .....	31
5.512.6	When the intersection of two planes is at 90° to another plane.....	31
5.512.7	When two straight lines, each formed by the intersection of two planes, are at 90° to each other .....	31
5.513	Tolerance.....	31
5.52	Perpendicularity of motion .....	31
5.521	Definition .....	31
5.522	Methods of measurement.....	31
5.522.1	General .....	31
5.522.2	Perpendicularity between the trajectory of a point and a plane.....	32
5.522.3	Trajectory of a point at 90° to an axis .....	32
5.522.4	Two trajectories perpendicular to each other .....	32
5.523	Tolerance.....	32
5.6	Rotation .....	32

5.61	Run-out .....	33
5.611	Definitions .....	33
5.611.1	Out-of-round.....	33
5.611.2	Eccentricity .....	33
5.611.3	Radial throw of an axis at a given point .....	33
5.611.4	Run-out of a component at a given section.....	33
5.612	Methods of measurement .....	33
5.612.1	Precautions before testing .....	33
5.612.2	External surface .....	34
5.612.3	Internal surface .....	34
5.613	Tolerance.....	34
5.62	Periodic axial Slip .....	35
5.621	Definitions .....	35
5.621.1	Minimum axial play.....	35
5.621.2	Periodic axial Slip.....	35
5.622	Methods of measurement .....	35
5.622.1	General.....	35
5.622.2	Applications .....	35
5.623	Tolerance .....	35
5.63	Camming.....	36
5.631	Definitions .....	36
5.632	Method of measurement .....	36
5.633	Tolerance.....	36
6	Special tests.....	37
6.1	Division .....	37
6.11	Definition of errors .....	37
6.111	Individual error of division.....	37
6.112	Successive error of division.....	37
6.1	13 Local error of division .....	37
6.114	Cumulative error .....	37
6.115	Total error of division.....	37
6.116	Graphical representation of these errors.....	37
6.12	Methods of measurement .....	39
6.13	Tolerance .....	39
6.2	Determination of the linear positioning deviations of screw-driven components .....	39
6.3	Angular play .....	39
6.31	Definition .....	39
6.32	Method of measurement (testing of the indexing device/component) .....	39
6.33	Tolerance .....	39
6.4	Repeatability of devices with angular indexing.....	39
6.41	Definition .....	39
6.42	Method of measurement .....	40
6.43	Tolerance .....	40
6.5	Intersection of axes .....	40
6.51	Definition .....	40
6.52	Methods of measurement .....	40
6.521	Direct measurement .....	40
6.522	Indirect measurement .....	40
6.53	Tolerance .....	40
6.6	Circularity .....	40
6.61	Definition .....	40
6.62	methods of measurement on test pieces.....	40
6.621	Circularity measuring machine with rotating pickup or rotating table .....	40
6.622	Coordinate measuring machine .....	41
6.623	Projection of the profile .....	41
6.624	Vee-block method.....	41
6.63	Measurement of numerically controlled (NC) circular movements.....	41
6.631	Rotating one-dimensional probe .....	41
6.632	Circular master and two-dimensional probe .....	41
6.633	Telescopic ball bar .....	43
6.7	Cylindricity .....	43

6.71	Definition .....	43
6.72	Methods of measurement.....	43
6.721	Coordinate measuring machine.....	43
6.722	Circularity measuring machine with rotating pickup or rotating table.....	44
6.723	Vee-block method .....	44
6.8	Consistency of machined diameters.....	44
6.81	Definition .....	44
6.82	Methods of measurement.....	44
6.821	Micrometer or similar two-point measuring Instrument .....	44
6.822	Height gauge.....	44

## Annexes

A	Instruments and equipment for testing machine tools.....	45
A.1	General.....	45
A.2	Straightedges .....	45
A.3	Test mandrels with taper shanks .....	46
A.4	Mandrels between centres .....	51
A.5	Squares.....	52
A.6	Precision levels.....	54
A.7	Linear displacement probes .....	55
A.8	Surface plates .....	56
A.9	Microscopes with taut-wire.....	56
A.10	Alignment telescopes.....	57
A.11	Autocollimators.....	58
A.12	Sweep optical squares .....	59
A.13	Laser interferometers .....	59
B	Bibliograph .....	62