

# ISO 230-4:2022-02 (E)

## Test code for machine tools - Part 4: Circular tests for numerically controlled machine tools

---

<b>Contents</b>		<b>Page</b>
<b>Foreword</b> .....		<b>iv</b>
<b>1</b>	<b>Scope</b> .....	<b>1</b>
<b>2</b>	<b>Normative references</b> .....	<b>1</b>
<b>3</b>	<b>Terms and definitions</b> .....	<b>1</b>
<b>4</b>	<b>Test conditions</b> .....	<b>6</b>
4.1	Test environment.....	6
4.2	Machine to be tested.....	6
4.3	Machine warm-up.....	6
4.4	Test parameters.....	6
4.5	Test instrument calibration.....	7
4.6	Measurement uncertainty.....	7
<b>5</b>	<b>Test procedure</b> .....	<b>7</b>
<b>6</b>	<b>Presentation of results</b> .....	<b>8</b>
<b>7</b>	<b>Points to be agreed between supplier or manufacturer and user</b> .....	<b>8</b>
<b>Annex A (informative) Differences between circular errors <math>G</math> and <math>G(b)</math> and radial errors <math>F</math> and <math>D</math></b> .....		<b>12</b>
<b>Annex B (informative) Influences of typical machine errors on circular paths executed with two linear axes</b> .....		<b>13</b>
<b>Annex C (informative) Precautions for test set-ups for circular tests with rotary axes</b> .....		<b>19</b>
<b>Annex D (informative) Adjustment of diameter and contouring speed for circular tests</b> .....		<b>24</b>
<b>Annex E (informative) Circular tests using feedback signal</b> .....		<b>25</b>
<b>Bibliography</b> .....		<b>26</b>