

# ISO 841:2001-10 (E)

## Industrial automation systems and integration - Numerical control of machines - Coordinate system and motion nomenclature

---

| <b>Contents</b>            |   | <b>Page</b> |
|----------------------------|---|-------------|
| Foreword .....             |   | iv          |
| Introduction .....         |   | v           |
| <b>1</b>                   | <b>Scope .....</b>                          | <b>1</b>    |
| <b>2</b>                   | <b>Normative references .....</b>           | <b>1</b>    |
| <b>3</b>                   | <b>Terms and definitions .....</b>          | <b>1</b>    |
| <b>4</b>                   | <b>Machine coordinate system .....</b>      | <b>1</b>    |
| 4.1                        | Designation .....                           | 1           |
| 4.2                        | Origin .....                                | 2           |
| 4.3                        | Z axis .....                                | 2           |
| 4.4                        | X axis .....                                | 2           |
| 4.5                        | Y axis .....                                | 3           |
| 4.6                        | Rotary axes A, B and C .....                | 3           |
| <b>5</b>                   | <b>Principal machine motions .....</b>      | <b>3</b>    |
| 5.1                        | Designation .....                           | 3           |
| 5.2                        | Direction .....                             | 3           |
| <b>6</b>                   | <b>Additional motions .....</b>             | <b>4</b>    |
| 6.1                        | Linear motions .....                        | 4           |
| 6.2                        | Rotary motion .....                         | 4           |
| 6.3                        | Letter restrictions .....                   | 4           |
| 6.4                        | Direction .....                             | 4           |
| <b>7</b>                   | <b>Schematic drawings of machines .....</b> | <b>4</b>    |
| 7.1                        | Examples of machine drawings .....          | 4           |
| 7.2                        | Designation .....                           | 5           |
| <b>Annex A (normative)</b> | <b>Examples of machine motions .....</b>    | <b>6</b>    |