

ISO 11877:2008-06 (E)

Hardmetals - Determination of silicon in cobalt metal powders - Photometric method

Contents		Page
	Foreword	iv
1	Scope	1
2	Principle	1
3	Reagents	1
4	Apparatus and equipment	2
5	Preparation of acid mixture for sample treatment	2
6	Preparation of solutions for receiver	2
7	Procedure	2
8	Photometric determination	3
9	Preparation of blank and calibration solutions	3
10	Expression of the result	3
11	Test report	3
	Bibliography	4