

# ISO/ASTM 52921:2013-06 (E)

## Standard terminology for additive manufacturing - Coordinate systems and test methodologies

---

<b>Contents</b>		<b>Page</b>
1	Scope .....	1
2	Referenced Documents .....	1
3	Significance and Use .....	1
4	Terminology .....	1
5	Keywords .....	3
Annex	.....	4
Figure A1.1	Generic (Upward Building) Additive Manufacturing Machine/System .....	4
Figure A1.2	Generic (Downward Building) Additive Manufacturing Machine/System .....	4
Figure A1.3	Right Hand Rule for Positive Rotations with Reference to the Build Volume Origin .....	5
Figure A1.4	Example of an Arbitrarily Oriented Minimum Bounding Box .....	5
Figure A1.5	Examples of Different Types of Bounding Boxes .....	6
Figure A1.6	Initial Build Orientation .....	7
Figure A1.7	Why is a Picture Normally Required to Communicate the Initial Build Orientation? .....	8
Figure A1.8	Orthogonal Orientation Notation .....	9
Figure A1.9	Examples of Bilateral Symmetry .....	10
Figure A1.10	Examples where Symmetry Allows Abbreviation of Orthogonal Orientation Notation ..	11
Figure A1.11	Part Location and Initial Build Orientation: Five Round Bar Specimens with Z Orientation .....	11
Figure A1.12	Part Location and Reorientation: Round Bars Oriented at B+45 from Z and B-45 from Z .....	12
Table A1.1	Description of Part Locations and Orientations .....	12
Table A1.2	Description of Part Locations and Orientations .....	12
Table X1.1	Task Group Contributors .....	13