

ISO 15787:2016-09 (E)

Technical product documentation - Heat-treated ferrous parts - Presentation and indications

Contents		Page
Foreword	v	
Introduction	vi	
1 Scope	1	
2 Normative references	1	
3 Terms,definitions	1	
4 Abbreviated terms	2	
5 Indications in drawings	2	
5.1 General	2	
5.2 Material data	3	
5.3 Heat-treatment condition	3	
5.4 Hardness data	3	
5.4.1 Surface hardness	3	
5.4.2 Core hardness	3	
5.4.3 Hardness value and limit deviations	3	
5.5 Markings	4	
5.5.1 Marking of test points	4	
5.5.2 Marking of slip zones	5	
5.6 Key for the allocation test point and nominal value	5	
5.7 Indication of local areas	5	
5.8 Hardness depth	6	
5.9 Carburizing depth (CD)	6	
5.10 Compound layer thickness (CLT)	7	
5.11 Oxide layer thickness (OLT)	7	
5.12 Strength data	8	
5.13 Microstructure	8	
5.14 Heat-treatment order (HTO)	8	
5.15 Heat-treatment document (HTD)	8	
6 Graphical representation	9	
6.1 General	9	
6.2 Heat-treatment of the entire part	9	
6.2.1 Uniform condition	9	
6.2.2 Areas with different conditions	9	
6.3 Local heat-treatment	9	
6.3.1 General	9	
6.3.2 Areas requiring heat-treatment	10	
6.3.3 Areas that may be heattreated	10	
6.3.4 Areas that shall not be heat-treated	10	
6.4 Heat-treatment sketch	11	
7 Practical examples	11	
7.1 General	11	
7.2 Quench-hardening, quench-hardening and tempering, austempering	11	
7.2.1 Heat-treatment of the entire part -- Allover uniform requirements	11	
7.2.2 Heat-treatment of the entire part -- Areas with different hardnesses	13	

7.2.3	Local heat-treatment	14
7.3	Surface-hardening	15
7.3.1	General	15
7.3.2	Specification of surface hardness	15
7.3.3	Specification of surfacehardening hardness depth (SHD)	15
7.3.4	Practical examples	15
7.4	Case-hardening	21
7.4.1	Specification of surface hardness	21
7.4.2	Specification of casehardening hardness depth (CHD)	21
7.4.3	Specification of carburizing depth (CD)	22
7.4.4	Practical examples	22
7.5	Nitriding and nitrocarburizing	27
7.5.1	Specification of nitriding hardness depth (NHD)	27
7.5.2	Specification of compound layer thickness (CLT)	27
7.5.3	Practical examples	28
7.6	Boriding	30
7.7	Annealing	30
	Annex A (normative) Graphical symbols	31
	Bibliography	33