

ISO 17295:2023-01 (E)

Additive manufacturing - General principles - Part positioning, coordinates and orientation

Contents		Page
Foreword		iv
Introduction		v
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
4	Machine coordinate systems for additive manufacturing machines with different build directions	1
4.1	General	1
4.2	Machine coordinate system for additive manufacturing machines with upwards Z-positive build direction	1
4.3	Machine coordinate system for additive manufacturing machines with downwards Z-positive build direction	2
5	Rule for positive direction of axes of rotation	3
6	Bounding box	3
7	Initial build orientation	4
8	Orthogonal orientation notation	6
8.1	General	6
8.2	Bilateral symmetry	7
8.3	Abbreviation of orthogonal orientation notation	8
9	Representation of part location and initial build orientation	8
10	Representation of part location and reorientation	9
Bibliography		12