

ISO/ASTM 52933:2024-03 (E)

Additive manufacturing - Environment, health and safety - Test method for the hazardous substances emitted from material extrusion type 3D printers in the non-industrial places

Contents		Page
Foreword		iv
Introduction		v
1	Scope	1
2	Normative references	1
3	Terms and definitions	2
4	Hazardous substance targets and major factors	3
5	Relevant test standards	3
6	Sampling conditions	4
6.1	Sampling location	4
6.2	Sampling planning	4
7	Measurement methods	6
7.1	Active and time-integrated methods	6
7.1.1	Purpose	6
7.1.2	VOCs analysis	6
7.1.3	Aldehyde method	9
7.2	Real-time method	11
7.2.1	Purpose	11
7.2.2	Sampling	11
7.2.3	Determination of particles concentration	11
8	Test report	13
Annex A (informative)	Considerations for reducing the emission of hazardous substances	15
Annex B (informative)	Checklist for reduction of hazardous substances	22
Bibliography		23