

ISO/ASTM 52933:2024-03 (E)

Additive manufacturing - Environment, health and safety - Test method for the hazardous substances emitted from material extrusion type 3D printers in the non-industrial places

Contents

Page

Foreword..... **iv**

Introduction..... **v**

1 Scope..... **1**

2 Normative references..... **1**

3 Terms and definitions..... **2**

4 Hazardous substance targets and major factors..... **3**

5 Relevant test standards..... **3**

6 Sampling conditions..... **4**

 6.1 Sampling location..... 4

 6.2 Sampling planning..... 4

7 Measurement methods..... **6**

 7.1 Active and time-integrated methods..... 6

 7.1.1 Purpose..... 6

 7.1.2 VOCs analysis..... 6

 7.1.3 Aldehyde method..... 9

 7.2 Real-time method..... 11

 7.2.1 Purpose..... 11

 7.2.2 Sampling..... 11

 7.2.3 Determination of particles concentration..... 11

8 Test report..... **13**

Annex A (informative) Considerations for reducing the emission of hazardous substances..... **15**

Annex B (informative) Checklist for reduction of hazardous substances..... **22**

Bibliography..... **23**