

# DIN EN ISO/ASTM 52953:2026-01 (E)

## Additive manufacturing for metals - General principles - Registration of data acquired from process monitoring and for quality control (ISO/ASTM 52953:2025)

---

<b>Contents</b>		<b>Page</b>
Foreword		iv
Introduction		v
<b>1</b>	<b>Scope</b>	<b>1</b>
<b>2</b>	<b>Normative reference</b>	<b>1</b>
<b>3</b>	<b>Terms, definitions and abbreviated terms</b>	<b>1</b>
	3.1 Terms and definitions	1
	3.2 Abbreviated terms	2
<b>4</b>	<b>Significance and use</b>	<b>3</b>
<b>5</b>	<b>Data registration procedure</b>	<b>3</b>
<b>6</b>	<b>Sensor categorization and metadata items</b>	<b>4</b>
	6.1 Sensor categorization	4
	6.2 Metadata in in-situ measurement	4
	6.2.1 Laser-scanning-related data elements	4
	6.2.2 Layer-wise images	5
	6.2.3 Registering melt pool monitoring images	6
	6.3 Ex-situ XCT measurements metadata elements	7
	6.4 Sources of uncertainty	7
<b>7</b>	<b>Data alignment with coordinate system transformations</b>	<b>8</b>
	7.1 General	8
	7.2 Methodology overview	8
	7.3 Melt pool image, scan path, and layer-wise image alignment	10
	7.3.1 General	10
	7.3.2 Melt pool image to scan path alignment	10
	7.3.3 Scan path to build platform alignment	12
	7.3.4 Layer-wise image to the build platform alignment	13
	7.4 Layer-wise images alignment	14
	7.5 Layer-wise images to the related XCT model alignment	15
	7.6 CMM Model to CAD model alignment	16
	7.7 Global coordinate system	17
	<b>Annex A (informative) Sensors and inspection systems categorization</b>	<b>18</b>
	<b>Annex B (informative) Examples of candidate global coordinate systems</b>	<b>21</b>
	<b>Annex C (informative) Edge fitting</b>	<b>22</b>
	<b>Bibliography</b>	<b>24</b>