

# ISO 9073-10:2003-05 (E)

## Textiles - Test methods for nonwovens - Part 10: Lint and other particles generation in the dry state

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
1	Scope .....	1
2	Normative references .....	1
3	Terms and definitions .....	1
4	Principle .....	1
5	Apparatus .....	2
6	Procedure .....	5
7	Calculation .....	6
8	Test report .....	7
Annex A (informative) General information regarding reproducibility .....		8
Annex B (informative) Worked example -- Total linting -- Sample X .....		9