

# ISO 3758:2005-04 (E)

## Textiles - Care labelling code using symbols

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
Introduction .....		v
1 <b>Scope</b> .....		1
2 <b>Terms and definitions</b> .....		1
3 <b>Description and definition of symbols</b> .....		3
4 <b>Application and use of symbols</b> .....		9
<b>Annex A (informative) Characteristics and available test methods for the correct selection of care symbols</b> .....		11
<b>Annex B (informative) Regional and national practices in care labelling</b> .....		16
<b>Annex C (informative) Symbols for natural drying</b> .....		19
<b>Annex D (informative) Examples of additional wording</b> .....		21
<b>Bibliography</b> .....		22