

ISO 18589-6:2009-03 (E)

Measurement of radioactivity in the environment - Soil - Part 6: Measurement of gross alpha and gross beta activities

Contents		Page
Foreword		iv
Introduction		v
1	Scope	1
2	Normative references	1
3	Terms, definitions and symbols	1
4	Principle	2
5	Chemical reagents and equipment	2
6	Procedure	3
7	Expression of results	5
8	Test report	8
Annex A (informative) Preparation of calibration sources with plutonium 239		10
Bibliography		12