

ISO 19581:2017-10 (E)

Measurement of radioactivity - Gamma emitting radionuclides - Rapid screening method using scintillation detector gamma-ray spectrometry

Contents		Page
Foreword		iv
Introduction		v
1	Scope	1
2	Normative references	1
3	Terms and definitions	2
4	Symbols and units	3
5	Principle	4
6	Apparatus	6
7	Sample container	7
8	Procedure	7
8.1	Packaging of samples for measuring purposes	7
8.2	Calibration	8
8.2.1	General	8
8.2.2	Reference source	8
8.2.3	Check source	8
8.2.4	Energy calibration	8
8.2.5	Detection efficiency calibration	9
8.3	Validation of the screening level	11
8.4	Screening procedure	11
8.4.1	Total spectrum counting / Single channel analyser counting	11
8.4.2	Multichannel analyser counting	12
8.4.3	Effect of sample density	13
9	Test report	13
Bibliography		18