

ISO/TS 11665-12:2018 (E)

Measurement of radioactivity in the environment — Air: radon-222 — Part 12: Determination of the diffusion coefficient in waterproof materials: membrane one-side activity concentration measurement method

Contents

| | |
|---------|---|
| | Foreword |
| | Introduction |
| 1 | Scope |
| 2 | Normative references |
| 3 | Terms, definitions and symbols |
| 3.1 | Terms and definitions |
| 3.2 | Symbols |
| 4 | Principle |
| 5 | Equipment |
| 6 | Sample preparation |
| 6.1 | General consideration |
| 6.2 | Fixing the sample in the holder |
| 6.3 | Connection of the holder (cap) with the chamber |
| 7 | Control measurements |
| 7.1 | Verification of radon-tightness |
| 7.2 | Calibration |
| 7.3 | Detector background |
| 7.4 | Instrument statistical fluctuation |
| 8 | Measurement of radon activity concentration |
| 9 | Processing and expression of the results for the sample |
| 9.1 | Determination of the radon diffusion coefficient in the sample |
| 9.2 | Characteristics of measurement limits |
| 9.3 | Estimation of confidence interval and uncertainty |
| 9.4 | Expression of the results |
| 10 | Requirements for the test |
| 11 | Influencing factors |
| 12 | Expression of the results and assessment of the standard uncertainty for the material |
| 13 | Quality management and calibration of the test device |
| 14 | Test report |
| 14.1 | The test report for material |
| 14.2 | The test report for each sample |
| 14.3 | Archived material |
| Annex A | (informative) Determination of the radon diffusion coefficient of the sample |
| A.1 | Scope |
| A.2 | Method of calculation of radon activity concentration in the source-detect chamber |

- A.3** **Example: Determination of the radon diffusion coefficient of the sample from the waterproof material (polyolefin) with a thickness of 0,60 mm**
- A.4** **Example: the statistical uncertainty of the test results of different materials**
- A.5** **Example: the parameters and design of the calibrated hole**

Page count: 27