

ISO 6980-3:2022-10 (E)

Nuclear energy - Reference beta-particle radiation - Part 3: Calibration of area and personal dosimeters and the determination of their response as a function of beta radiation energy and angle of incidence

Contents		Page
Foreword		iv
Introduction		v
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
4	Symbols and abbreviated terms, and reference and standard test conditions	3
5	Procedures applicable to all area and personal dosimeters	4
5.1	General principles	4
5.1.1	Selection of sources and radiation qualities	4
5.1.2	Reference absorbed dose rate	4
5.1.3	Conversion coefficients	5
5.1.4	Reference conditions and standard test conditions	5
5.1.5	Variation of influence quantities	5
5.1.6	Point of test and reference point	6
5.1.7	Axes of rotation	6
5.1.8	Condition of the dosimeter to be calibrated	6
5.1.9	Influence of photon contribution	6
5.2	Determination of the calibration factors and of the correction factors	6
5.2.1	Determination of the reference dose rate by a standard instrument	6
5.2.2	Determination of reference calibration factor and correction factor for non-linear response	7
5.2.3	Determination of the correction factor for beta-particle energy and angle of incidence, k_E ,	7
6	Particular procedures for area dosimeters	8
6.1	General principles	8
6.2	Quantity to be measured	8
7	Particular procedures for personal dosimeters	8
7.1	General principles	8
7.2	Quantity to be measured	8
7.3	Experimental conditions	8
7.3.1	Use of phantoms	8
7.3.2	Geometrical considerations in divergent beams	9
7.3.3	Simultaneous irradiation of several dosimeters	9
8	Uncertainties	10
9	Reporting of results according to ISO 17025	10
Annex A (normative) Reference conditions and standard test conditions		11
Annex B (informative) Conversion coefficients for some beta reference radiation fields		13
Bibliography		19