

ISO 11929-6:2005-02 (E)

Determination of the detection limit and decision threshold for ionizing radiation measurements - Part 6: Fundamentals and applications to measurements by use of transient mode

Contents		Page
Foreword		iv
Introduction		v
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
4	Quantities and symbols	3
5	Statistical values and confidence interval	5
5.1	Principles	5
5.1.1	General aspects	5
5.1.2	Model	6
5.2	Decision threshold	7
5.3	Detection limit	8
5.4	Confidence limits	9
6.1	Specific values	9
6.2	Assessment of a measuring method	9
6.3	Assessment of measured results	9
6.4	Documentation	10
7	Values of the distribution function of the standardized normal distribution	10
Bibliography		16