

# ISO/TS 9516-2:2024-05 (E)

## Iron ores - Determination of various elements by X-ray fluorescence spectrometry - Part 2: Single element calibration procedure

---

<b>Contents</b>		<b>Page</b>
Foreword .....		v
1	Scope .....	1
2	Normative references .....	1
3	Terms and definitions .....	1
4	Principle .....	2
5	Reagents and materials .....	2
6	Apparatus .....	4
7	Sampling and samples .....	5
7.1	Laboratory sample .....	5
7.2	Preparation of test samples .....	5
7.2.1	General .....	5
7.2.2	Method specified in ISO 2596 .....	5
7.2.3	Method specified in ISO 7764 .....	6
8	Procedure .....	6
8.1	General .....	6
8.2	Number of determinations .....	7
8.3	Check analysis and blank test .....	7
8.4	Preparation of discs .....	7
8.4.1	Weighing .....	7
8.4.2	Mixing .....	8
8.4.3	Fusion .....	8
8.4.4	Casting .....	8
8.4.5	Visual inspection .....	8
8.4.6	Disc storage .....	8
8.4.7	Cleaning of platinum ware .....	9
8.4.8	Test discs .....	9
8.5	Measurement .....	9
8.5.1	General .....	9
8.5.2	Effect of errors or omissions .....	10
8.5.3	Analytical lines .....	11
8.5.4	XRF generator settings .....	11
8.5.5	Crystals .....	14
8.5.6	Line overlaps .....	14
8.5.7	Collimators .....	14
8.5.8	Pulse height settings .....	14
8.5.9	Counting time .....	14
8.5.10	Simultaneous instruments .....	15
8.5.11	Sample holders .....	15
8.5.12	Measurement sequence .....	16
8.6	Drift correction .....	16
8.6.1	Preparation of drift correction monitor discs .....	16
8.6.2	Drift correction using monitor disc .....	17

9	Calculation of results .....	19
9.1	General .....	19
9.2	Calibration equation .....	20
9.3	Calculation of alpha coefficient .....	23
9.4	Correction for sample, flux and oxidizer mass .....	24
9.4.1	General .....	24
9.4.2	Correction of flux/sample mass ratio .....	24
9.4.3	Correction of remaining oxidizer/sample mass ratio .....	24
9.4.4	Mass ratio correction constant in calibration Equation 1 .....	25
9.5	Calculation of calibration .....	25
9.5.1	Preparation of calibration discs .....	25
9.5.2	Calculation of concentrations of calibration discs .....	28
9.5.3	Measurement of calibration discs .....	29
9.5.4	Calculation of calibration coefficients .....	29
9.6	Calculation of concentrations .....	33
9.6.1	Calculation of flux/sample and remaining oxidizer/sample mass ratios .....	33
9.6.2	Calculation of initial concentration .....	34
9.6.3	Calculation of concentrations .....	34
9.6.4	Conversion from oxide to element concentrations .....	35
10	General treatment of results .....	35
10.1	Background equivalent concentration (BEC) .....	35
10.2	Determination of analytical result .....	36
10.3	Check for trueness .....	36
10.4	Calculation of the final result .....	37
10.5	Oxide factors .....	38
11	Test report .....	38
Annex A (normative) Preparation of Flux A and Flux D .....		39
Annex B (normative) Preparation of Flux B and Flux C .....		41
Annex C (normative) Standard deviation of specimen preparation .....		42
Annex D (normative) Spectrometer precision tests .....		44
Annex E (informative) Theoretical derivation of correction term in calibration .....		48
Annex F (informative) Calculation of correction coefficients using the FP method (fundamental parameter method) .....		53
Annex G (informative) Calculation of calibration coefficients and correction alphas by the least square method .....		56
Annex H (informative) Calculation of counting time .....		60
Annex I (informative) Air cooling block for fused discs .....		63
Annex J (normative) Flowchart for acceptance of results .....		64
Bibliography .....		65