

# ISO/TR 20491:2019-02 (E)

## Fasteners - Fundamentals of hydrogen embrittlement in steel fasteners

---

<b>Contents</b>	<b>Page</b>
Foreword .....	iv
Introduction .....	v
<b>1 Scope .....</b>	<b>1</b>
<b>2 Normative references .....</b>	<b>1</b>
<b>3 Terms and definitions .....</b>	<b>1</b>
<b>4 Symbols and abbreviated terms .....</b>	<b>4</b>
<b>5 General description of hydrogen embrittlement .....</b>	<b>4</b>
<b>6 Hydrogen damage mechanism .....</b>	<b>4</b>
<b>7 Fracture morphology .....</b>	<b>5</b>
<b>8 Conditions at the tip of a crack .....</b>	<b>7</b>
<b>9 Conditions for hydrogen embrittlement failure .....</b>	<b>7</b>
9.1 Root cause and triggers for hydrogen embrittlement failure .....	7
9.2 Material susceptibility .....	8
9.2.1 General .....	8
9.2.2 Defects and other conditions causing abnormal material susceptibility .....	10
9.2.3 Methodology for measuring HE threshold stress .....	10
9.3 Tensile stress .....	11
9.4 Atomic hydrogen .....	12
9.4.1 Sources of hydrogen .....	12
9.4.2 Internal hydrogen .....	12
9.4.3 Environmental hydrogen .....	13
<b>10 Case-hardened fasteners .....</b>	<b>13</b>
<b>11 Hot dip galvanizing and thermal up-quenching .....</b>	<b>15</b>
<b>12 Stress relief prior to electroplating .....</b>	<b>16</b>
<b>13 Fasteners thread rolled after heat treatment .....</b>	<b>16</b>
<b>14 Hydrogen embrittlement test methods .....</b>	<b>17</b>
<b>15 Baking .....</b>	<b>17</b>
<b>Bibliography .....</b>	<b>19</b>