

# ISO 14617-6:2002-09 (E)

## Graphical symbols for diagrams - Part 6: Measurement and control functions

---

| <b>Contents</b>                                          | <b>Page</b> |
|----------------------------------------------------------|-------------|
| Foreword .....                                           | iv          |
| Introduction .....                                       | v           |
| 1      Scope .....                                       | 1           |
| 2      Normative references .....                        | 1           |
| 3      Terms and definitions .....                       | 2           |
| 4      Functional links and junctions .....              | 3           |
| 5      Point of measurement .....                        | 5           |
| 6      Operation of final controlling elements .....     | 5           |
| 7      Information-processing functions .....            | 10          |
| 8      Binary logic functions .....                      | 20          |
| 9      Back-up functions .....                           | 20          |
| 10     Examples of use of symbols in control loops ..... | 21          |
| Bibliography .....                                       | 23          |