

ISO 877-2:2009-06 (E)

Plastics - Methods of exposure to solar radiation - Part 2: Direct weathering and exposure behind window glass

Contents		Page
Foreword		iv
1	Scope	1
2	Normative references	1
3	Principle	1
4	Apparatus	1
5	Test specimens	3
6	Conditions of exposure of the test specimens	4
7	Exposure stages	4
8	Procedure	5
9	Expression of results	6
10	Test report	6