

# ISO 11358-1:2014-07 (E)

## Plastics - Thermogravimetry (TG) of polymers - Part 1: General principles

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
<b>1</b>	<b>Scope .....</b>	<b>1</b>
<b>2</b>	<b>Normative references .....</b>	<b>1</b>
<b>3</b>	<b>Terms and definitions .....</b>	<b>1</b>
<b>4</b>	<b>Principle .....</b>	<b>2</b>
<b>5</b>	<b>Apparatus .....</b>	<b>2</b>
<b>6</b>	<b>Test specimen preparation .....</b>	<b>2</b>
<b>6.1</b>	<b>General .....</b>	<b>2</b>
<b>6.2</b>	<b>Test specimens from finished products .....</b>	<b>3</b>
<b>6.3</b>	<b>Test specimen conditioning .....</b>	<b>3</b>
<b>6.4</b>	<b>Test specimen mass .....</b>	<b>3</b>
<b>7</b>	<b>Calibration .....</b>	<b>3</b>
<b>7.1</b>	<b>Mass calibration .....</b>	<b>3</b>
<b>7.2</b>	<b>Temperature calibration .....</b>	<b>3</b>
<b>8</b>	<b>Procedure .....</b>	<b>4</b>
<b>8.1</b>	<b>General .....</b>	<b>4</b>
<b>8.2</b>	<b>Temperature scanning mode .....</b>	<b>4</b>
<b>8.3</b>	<b>Isothermal mode .....</b>	<b>5</b>
<b>9</b>	<b>Expression of results .....</b>	<b>5</b>
<b>9.1</b>	<b>Graphical representation .....</b>	<b>5</b>
<b>9.2</b>	<b>Determination of increase in mass .....</b>	<b>5</b>
<b>9.3</b>	<b>Determination of loss in mass .....</b>	<b>6</b>
<b>10</b>	<b>Test report .....</b>	<b>8</b>