

DIN EN 16795:2016-03 (E)

Plastics - Method for estimating heat build up of flat surfaces by simulated solar radiation

Contents	Page
European foreword	3
Introduction	4
1 Scope	5
2 Normative references	5
3 Terms and definitions	5
4 Abbreviations	5
5 Principle	5
6 Apparatus	6
6.1 General	6
6.2 Test chamber	6
6.3 Laboratory radiation source	6
6.4 Radiometer	7
6.5 Test chamber temperature and relative humidity	7
6.6 Surface temperature measurement device	7
6.7 Black and white standard thermometer	8
6.8 Defined airflow directed across the sample	9
6.9 Specimen holders	9
7 Test specimens	9
7.1 Form, shape and preparation	9
7.2 Number of test specimens	9
8 Exposure conditions	9
8.1 Radiation	9
8.2 Black and white standard thermometer	9
8.3 Chamber air temperature	10
8.4 Relative humidity of chamber air	10
8.5 Wind speed	10
8.6 Sets of exposure conditions	10
9 Procedure	10
9.1 General	10
9.2 Mounting the test specimens	10
9.3 Exposure	10
9.4 Measurement of the surface temperature	11
10 Test report	11
Bibliography	12