

# ISO 6721-11:2019 (E)

## Plastics — Determination of dynamic mechanical properties — Part 11: Glass transition temperature

---

### Contents

	Foreword
	Introduction
1	Scope
2	Normative references
3	Terms and definitions
4	Principle
5	Apparatus
5.1	Test equipment
5.2	Devices for measuring test specimen dimensions
6	Test specimen
6.1	General
6.2	Shape and dimensions
6.3	Preparation
7	Number of specimens
8	Conditioning
9	Test procedure
9.1	Test atmosphere
9.2	Operation
9.2.1	Method A — Rate-dependent results — Full procedure
9.2.2	Offset method — Rate dependent results
9.2.3	Method B — Rate-independent results
10	Expression of results
11	Precision
12	Test report
Annex A	(normative) Calibration procedures
A.1	Equipment calibration
A.2	Temperature calibration
Annex B	(informative) Assessment of heating rate sensitivity using reference sample
B.1	Assessment procedure
B.1.1	General
B.1.2	Flexure or torsion
B.1.3	Tension
B.1.4	Shear and compression
B.2	Data analysis
B.3	Interlaboratory trial