

<b>Contents</b>		<b>Page</b>
Foreword.....		iv
Introduction.....		v
<b>1 Scope.....</b>		<b>1</b>
<b>2 Normative references.....</b>		<b>1</b>
<b>3 Terms and definitions.....</b>		<b>1</b>
<b>4 Requirements.....</b>		<b>2</b>
4.1 Dimension deviation.....		2
4.1.1 Types and dimensions.....		2
4.1.2 Thickness and deviation.....		3
4.1.3 Width deviation.....		4
4.1.4 Length deviation.....		4
4.2 Print quality.....		5
4.2.1 Appearance of print.....		5
4.2.2 Stripping rate.....		5
4.3 Physical and mechanical properties.....		5
4.4 Industrial compostability.....		6
<b>5 Test methods.....</b>		<b>6</b>
5.1 Sample condition adjustment and test environment.....		6
5.2 Dimension deviation.....		6
5.2.1 Thickness deviation.....		6
5.2.2 Width and length deviation.....		7
5.3 Print quality.....		7
5.3.1 Print appearance.....		7
5.3.2 Stripping rate.....		7
5.4 Physical and mechanical properties.....		8
5.4.1 Stress at break (only for class II).....		8
5.4.2 Lifting test.....		8
5.4.3 Drop test (only for class I).....		8
5.4.4 Water leakage test.....		9
5.4.5 Sealing strength test.....		9
5.4.6 Dart impact test.....		10
5.5 Industrial compostability.....		10
<b>6 Testing regulations.....</b>		<b>10</b>
6.1 Batch.....		10
6.2 Inspection classification.....		10
6.2.1 Factory inspection.....		10
6.2.2 Type test.....		11
6.3 Sampling plan.....		11
6.3.1 Dimensional deviation.....		11
6.3.2 Print quality, physical and mechanical properties, industrial compostability.....		11
6.4 Decision rule.....		12
6.4.1 Qualification.....		12
6.4.2 Determination of qualified batch.....		12
<b>7 Packaging, labelling on packaging, transportation, storage.....</b>		<b>12</b>
7.1 Package.....		12
7.2 Mark on packaging.....		12
7.3 Transport.....		12
7.4 Storage.....		13
<b>Bibliography.....</b>		<b>14</b>