

ISO 3672-2:2000-07 (E)

Plastics - Unsaturated-polyester resins (UP-R) - Part 2: Preparation of test specimens and determination of properties

Contents		Page
Foreword		iv
Introduction		v
1	Scope	1
2	Normative references	1
3	Preparation of test specimens	3
3.1	General	3
3.2	Pretreatment of materials	3
3.3	Preparation of the sheets	4
3.4	Cutting out test specimens	6
4	Conditioning of test specimens	6
5	Determination of properties	6