

# ISO 5659:2026-01 (E)

## Plastics - Smoke generation - Determination of optical density by a single-chamber test

---

### Contents

	Page
Foreword.....	v
Introduction.....	vi
<b>1 Scope.....</b>	<b>1</b>
<b>2 Normative references.....</b>	<b>1</b>
<b>3 Terms and definitions.....</b>	<b>1</b>
<b>4 Principles of the test.....</b>	<b>3</b>
<b>5 Suitability of a material or product for testing.....</b>	<b>3</b>
5.1 Material or product geometry.....	3
5.2 Surface characteristics.....	3
5.3 Asymmetrical products.....	3
<b>6 Specimen construction and preparation.....</b>	<b>4</b>
6.1 Number of specimens.....	4
6.2 Size of specimens.....	4
6.3 Specimen preparation.....	4
6.4 Conditioning.....	5
6.5 Wrapping of specimens.....	5
6.6 Dimensionally unstable materials.....	5
<b>7 Apparatus and ancillary equipment.....</b>	<b>6</b>
7.1 General.....	6
7.2 Test chamber.....	6
7.2.1 Construction.....	6
7.2.2 Chamber pressure control facilities.....	7
7.2.3 Chamber wall temperature.....	10
7.3 Specimen support and heating arrangements.....	11
7.3.1 Radiator cone.....	11
7.3.2 Framework for support of the radiator cone, specimen holder and heat flux meter.....	11
7.3.3 Radiation shield.....	14
7.3.4 Heat flux meter.....	14
7.3.5 Specimen holder.....	14
7.3.6 Pilot burner.....	15
7.4 Gas supply.....	15
7.5 Photometric system.....	16
7.5.1 General.....	16
7.5.2 Light source.....	16
7.5.3 Photo detector.....	16
7.5.4 Additional equipment.....	18
7.6 Chamber leakage.....	18
7.7 Cleaning materials.....	19
7.8 Ancillary equipment.....	19
7.8.1 Balance (optional).....	19
7.8.2 Timing device.....	19
7.8.3 Linear measuring devices.....	19
7.8.4 Auxiliary heater.....	19
7.8.5 Protective equipment.....	19
7.8.6 Recorder.....	19
7.8.7 Water-circulating device.....	19
7.8.8 Oxygen meter (optional).....	19

<b>8</b>	<b>Test environment</b> .....	<b>20</b>
<b>9</b>	<b>Setting-up and calibration procedures</b> .....	<b>20</b>
	9.1 General.....	20
	9.2 Alignment of photometric system.....	20
	9.2.1 General.....	20
	9.2.2 Beam collimation.....	20
	9.2.3 Beam focusing.....	20
	9.3 Selection of compensating filter(s).....	21
	9.4 Linearity check.....	21
	9.5 Calibration of range-extension filter.....	21
	9.6 Chamber leakage rate test.....	22
	9.7 Burner calibration.....	22
	9.8 Radiator cone calibration.....	22
	9.9 Cleaning.....	23
	9.10 Frequency of checking and calibrating procedure.....	23
<b>10</b>	<b>Test procedure</b> .....	<b>24</b>
	10.1 General.....	24
	10.2 Preparation of test chamber.....	24
	10.3 Tests with pilot flame.....	24
	10.4 Preparation of the photometric system.....	24
	10.5 Loading the specimen.....	25
	10.6 Recording of light transmission.....	25
	10.7 Observations.....	25
	10.8 Termination of test.....	25
	10.9 Testing in different modes.....	26
<b>11</b>	<b>Expression of results</b> .....	<b>26</b>
	11.1 Specific optical density, $D_s$ .....	26
	11.2 Clear-beam correction factor, $D_c$ .....	27
<b>12</b>	<b>Precision</b> .....	<b>27</b>
<b>13</b>	<b>Test report</b> .....	<b>27</b>
	<b>Annex A (normative) Calibration of heat flux meter</b> .....	<b>29</b>
	<b>Annex B (informative) Variability in the specific optical density of smoke measured in the single-chamber test</b> .....	<b>30</b>
	<b>Annex C (informative) Determination of mass optical density</b> .....	<b>32</b>
	<b>Annex D (informative) Precision data from tests on intumescent materials</b> .....	<b>37</b>
	<b>Annex E (informative) Guidance on optical density testing</b> .....	<b>39</b>
	<b>Annex F (informative) Specific sample preparation</b> .....	<b>46</b>
	<b>Annex G (informative) Background to standard reference materials</b> .....	<b>49</b>
	<b>Bibliography</b> .....	<b>50</b>