

# ISO 8988:2006-09 (E)

## Plastics - Phenolic resins - Determination of hexamethylenetetramine content - Kjeldahl method, perchloric acid method and hydrochloric acid method

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
1	Scope .....	1
2	Normative references .....	1
3	Kjeldahl method .....	1
4	Perchloric acid method .....	3
5	Hydrochloric acid method .....	5
6	Test report .....	7