

# DIN EN 13999-2:2007-07 (E)

Adhesives - Short term method for measuring the emission properties of low-solvent or solvent-free adhesives after application - Part 2: Determination of volatile organic compounds

---

| <b>Contents</b>                               |  | <b>Page</b> |
|---|--|-------------|
| Foreword .....                                |  | 3           |
| <b>SAFETY STATEMENT .....</b>                 |  | <b>4</b>    |
| <b>1 Scope .....</b>                          |  | <b>4</b>    |
| <b>2 Normative references .....</b>           |  | <b>4</b>    |
| <b>3 Principle .....</b>                      |  | <b>4</b>    |
| <b>4 Reagents and materials .....</b>         |  | <b>5</b>    |
| <b>5 Apparatus .....</b>                      |  | <b>5</b>    |
| <b>6 Procedure .....</b>                      |  | <b>6</b>    |
| <b>7 Identification and calculation .....</b> |  | <b>9</b>    |
| <b>8 Precision and bias .....</b>             |  | <b>11</b>   |
| <b>9 Test report .....</b>                    |  | <b>11</b>   |
| <b>10 Quality control .....</b>               |  | <b>12</b>   |
| <b>Bibliography .....</b>                     |  | <b>13</b>   |