

ISO 11790:2010-09 (E)

Copper, lead, zinc and nickel concentrates - Guidelines for the inspection of mechanical sampling systems

Contents		Page
Foreword		iv
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
4	General consideration	2
4.1	Precision	2
4.2	Quality variation	2
4.3	Bias	2
4.4	Operation of the sampling system	3
5	Establishment of inspection system	3
5.1	General	3
5.2	Audits	4
5.3	Mechanical inspections	4
5.4	Operational inspections	4
6	Procedures	4
6.1	Audits	4
6.2	Mechanical inspections	5
6.3	Operational inspections	6
6.4	Control charts	7
6.4.1	General	7
6.4.2	Sampling ratio	7
6.4.3	Extraction ratio	7
6.5	Sampling records	10
6.6	Operator's inspection report	10
Annex A (informative) Example of a sampling checklist for copper ore		11
Annex B (informative) Example of sampling plant operator's inspection report on a shift basis		14
Annex C (informative) Example of sampling-system operations inspection summary		18