

# ISO 11794:2010-10 (E)

## Copper, lead, zinc and nickel concentrates - Sampling of slurries

---

| <b>Contents</b> |  | <b>Page</b> |
|-----------------|--|-------------|
| Foreword .....  |  | v           |
| <b>1</b>        | <b>Scope .....</b>   | <b>1</b>    |
| <b>2</b>        | <b>Normative references .....</b>  | <b>1</b>    |
| <b>3</b>        | <b>Terms and definitions .....</b>   | <b>2</b>    |
| <b>4</b>        | <b>Principles of sampling slurries .....</b>                                 | <b>2</b>    |
| 4.1             | General .....  | 2           |
| 4.2             | Sampling errors .....  | 3           |
| 4.2.1           | General .....  | 3           |
| 4.2.2           | Preparation error, PE .....  | 4           |
| 4.2.3           | Delimitation and extraction errors, DE and EE .....                          | 4           |
| 4.2.4           | Weighting error, WE .....  | 6           |
| 4.2.5           | Periodic quality-fluctuation error, QE3 .....                                | 6           |
| 4.3             | Sampling and total variance .....  | 6           |
| 4.3.1           | Sampling variance .....  | 6           |
| 4.3.2           | Total variance .....   | 6           |
| 4.3.3           | Sampling-stage method of estimating sampling and total variance .....        | 8           |
| 4.3.4           | Simplified method of estimating sampling and total variance .....            | 9           |
| 4.3.5           | Interleaved sample method of measuring total variance .....                  | 10          |
| <b>5</b>        | <b>Establishing a sampling scheme .....</b>                                  | <b>11</b>   |
| <b>6</b>        | <b>Minimization of bias and unbiased increment mass .....</b>                | <b>16</b>   |
| 6.1             | Minimization of bias .....   | 16          |
| 6.2             | Volume of increment for falling-stream samplers to avoid bias .....          | 17          |
| <b>7</b>        | <b>Number of increments .....</b>  | <b>17</b>   |
| 7.1             | General .....  | 17          |
| 7.2             | Simplified method .....  | 18          |
| <b>8</b>        | <b>Minimum mass of solids contained in lot and sub-lot samples .....</b>     | <b>18</b>   |
| 8.1             | Minimum mass of solids in lot samples .....                                  | 18          |
| 8.2             | Minimum mass of solids in sub-lot samples .....                              | 18          |
| 8.3             | Minimum mass of solids in lot and sub-lot samples after size reduction ..... | 18          |
| <b>9</b>        | <b>Time-basis sampling .....</b>   | <b>19</b>   |
| 9.1             | General .....  | 19          |
| 9.2             | Sampling interval .....  | 19          |
| 9.3             | Cutters .....  | 19          |
| 9.4             | Taking of increments .....   | 19          |
| 9.5             | Constitution of lot or sub-lot samples .....                                 | 20          |
| 9.6             | Division of increments and sub-lot samples .....                             | 20          |
| 9.7             | Division of lot samples .....  | 20          |
| 9.8             | Number of cuts for division .....  | 20          |
| <b>10</b>       | <b>Stratified random sampling within fixed time intervals .....</b>          | <b>20</b>   |
| <b>11</b>       | <b>Mechanical sampling from moving streams .....</b>                         | <b>21</b>   |
| 11.1            | General .....  | 21          |

|  |  |    |
|--|--|----|
| 11.2   | Design of the sampling system .....              | 21 |
| 11.2.1   | Safety of operators .....                        | 21 |
| 11.2.2   | Location of sample cutters .....                 | 21 |
| 11.2.3   | Provision for duplicate sampling .....           | 21 |
| 11.2.4   | System for checking the precision and bias ..... | 21 |
| 11.2.5   | Avoiding bias .....                              | 22 |
| 11.3   | Slurry sample cutters .....                      | 22 |
| 11.3.1   | General .....                                    | 22 |
| 11.3.2   | Falling-stream cutters .....                     | 23 |
| 11.3.3   | Cutter velocities .....                          | 23 |
| 11.4   | Mass of solids in increments .....               | 23 |
| 11.5   | Number of primary increments .....               | 23 |
| 11.6   | Routine checking .....                           | 23 |
| 12   | Manual sampling from moving streams .....        | 24 |
| 12.1   | General .....                                    | 24 |
| 12.2   | Choosing the sampling location .....             | 24 |
| 12.3   | Sampling implements .....                        | 25 |
| 12.4   | Mass of solids in increments .....               | 25 |
| 12.5   | Number of primary increments .....               | 25 |
| 12.6   | Sampling procedures .....                        | 25 |
| 13   | Sampling of stationary slurries .....            | 26 |
| 14   | Sample preparation .....                         | 26 |
| 14.1   | General .....                                    | 26 |
| 14.2   | Sample division .....                            | 26 |
| 14.3   | Sample grinding .....                            | 26 |
| 14.4   | Chemical analysis samples .....                  | 26 |
| 14.5   | Physical test samples .....                      | 27 |
| 15   | Packing and marking of samples .....             | 27 |
| Annex A (normative) Sampling-stage method for estimating sampling and total variance ..... |  | 28 |
| Annex B (informative) Examples of correct slurry sampling devices .....                    |  | 34 |
| Annex C (informative) Examples of incorrect slurry sampling devices .....                  |  | 37 |
| Annex D (normative) Manual sampling implements .....                                       |  | 41 |
| Bibliography .....   |  | 42 |