

DIN EN 15616:2013-02 (E)

Copper and copper alloys - Determination of cadmium content - Flame atomic absorption spectrometric method (FAAS)

Contents		Page
Foreword		3
1 Scope		4
2 Normative references		4
3 Principle		4
4 Reagents		4
5 Apparatus		5
6 Sampling		5
7 Procedure		5
8 Expression of results		8
9 Precision		10
10 Test report		11
Bibliography		12