

DIN EN 15079:2015-07 (E)

Copper and copper alloys - Analysis by spark optical emission spectrometry (S-OES)

Contents		Page
Foreword		3
1	Scope	4
2	Normative references	4
3	Terms and definitions	4
4	Principle	5
5	Apparatus	5
5.1	Optical emission spectrometer	5
5.2	Apparatus for sample surface preparation	5
6	Sampling	5
7	Procedure	6
7.1	Surface preparation	6
7.2	Calibration procedures	6
7.2.1	General	6
7.2.2	Calibration	7
7.2.3	Recalibration	7
7.2.4	Type recalibration	7
7.3	Analysis	7
7.3.1	Preparation of analytical programs	7
7.3.2	Analysis method	8
7.3.3	Number of sparks on test samples	8
7.3.4	Status check of the apparatus	8
8	Expression of results	8
9	Precision	9
10	Test report	9
Annex A (informative)	Wavelengths for spectrometric analysis and typical calibration ranges for copper and copper alloys	10
Annex B (informative)	Wavelengths, background equivalent concentrations (BEC) and detection limits (DL) for pure copper	17
Bibliography		20