

# ISO 7530-1:2015-06 (E)

## Nickel alloys - Flame atomic absorption spectrometric analysis - Part 1: Determination of cobalt, chromium, copper, iron and manganese

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
Introduction .....		v
1	Scope .....	1
2	Normative references .....	1
3	Principle .....	1
4	Reagents .....	1
5	Apparatus .....	4
6	Sampling and sample preparation .....	4
7	Procedure .....	5
7.1	Test portion .....	5
7.2	Blank test .....	5
7.3	Dissolution .....	5
7.4	Determination of cobalt .....	5
7.4.1	Preparation of the test solution .....	5
7.4.2	Preparation of the calibration solutions .....	6
7.5	Determination of chromium .....	7
7.5.1	Preparation of the test solution .....	7
7.5.2	Preparation of the calibration solutions .....	8
7.6	Determination of copper .....	9
7.6.1	Preparation of the test solution .....	9
7.6.2	Preparation of the calibration solutions .....	9
7.7	Determination of iron .....	11
7.7.1	Preparation of the test solution .....	11
7.7.2	Preparation of the calibration solutions .....	12
7.8	Determination of manganese .....	13
7.8.1	Preparation of the test solution .....	13
7.8.2	Preparation of the calibration solutions .....	13
7.9	Adjustment of atomic absorption spectrometer .....	15
7.10	Spectrometric measurements .....	15
7.11	Calibration curves .....	16
7.12	Expression of results .....	16
7.13	Precision .....	16
7.13.1	General .....	16
7.13.2	Precision for cobalt .....	17
7.13.3	Precision for chromium .....	18
7.13.4	Precision for copper .....	18
7.13.5	Precision for iron .....	18
7.13.6	Precision for manganese .....	18
8	Test report .....	19
Annex A (normative)	Procedures for checking the instrumental criteria .....	20
Bibliography .....		23