

ISO 24181-1:2024-08 (E)

Rare earth - Determination of non-rare earth impurities in individual rare earth metals and their oxides - I CP-AES - Part 1: Analysis of Al, Ca, Mg, Fe and Si

Contents		Page
Foreword		iv
Introduction		v
1	Scope	1
2	Normative references	1
3	Terms and definitions	1
4	Principle	3
5	Reagent	4
6	Apparatus	4
6.1	Volumetric glassware	4
6.2	Inductively coupled plasma atomic emission spectrometer	4
6.2.1	General	4
6.2.2	Line spectra selection	4
7	Procedure	5
7.1	Weighing the test portion	5
7.2	Sample preparation	6
7.3	Preparation of calibration solutions	6
7.4	Measurements	7
7.4.1	Instrument set-up	7
7.4.2	Measurement of the calibration solution and calibration curve construction	7
7.4.3	Measurement of the test solution	7
8	Calculation and expression of results	7
8.1	Method of calculation	7
8.2	Precision	8
8.2.1	Interlaboratory test	8
8.2.2	Statistical analysis	8
9	Test report	8
Annex A (informative) Interlaboratory test results		9
Annex B (informative) Regression formulae of precision		10
Bibliography		11