

# ISO 24181-1:2024-08 (E)

## Rare earth - Determination of non-rare earth impurities in individual rare earth metals and their oxides - I CP-AES - Part 1: Analysis of Al, Ca, Mg, Fe and Si

---

<b>Contents</b>		<b>Page</b>
Foreword .....		iv
Introduction .....		v
1	Scope .....	1
2	Normative references .....	1
3	Terms and definitions .....	1
4	Principle .....	3
5	Reagent .....	4
6	Apparatus .....	4
6.1	Volumetric glassware .....	4
6.2	Inductively coupled plasma atomic emission spectrometer .....	4
6.2.1	General .....	4
6.2.2	Line spectra selection .....	4
7	Procedure .....	5
7.1	Weighing the test portion .....	5
7.2	Sample preparation .....	6
7.3	Preparation of calibration solutions .....	6
7.4	Measurements .....	7
7.4.1	Instrument set-up .....	7
7.4.2	Measurement of the calibration solution and calibration curve construction .....	7
7.4.3	Measurement of the test solution .....	7
8	Calculation and expression of results .....	7
8.1	Method of calculation .....	7
8.2	Precision .....	8
8.2.1	Interlaboratory test .....	8
8.2.2	Statistical analysis .....	8
9	Test report .....	8
Annex A (informative) Interlaboratory test results .....		9
Annex B (informative) Regression formulae of precision .....		10
Bibliography .....		11