

# DIN EN ISO 24181-1:2026-03 (E)

Rare earth - Determination of non-rare earth impurities in individual rare earth metals and their oxides - ICP-AES - Part 1: Analysis of Al, Ca, Mg, Fe and Si (ISO 24181-1:2024)

---

## Contents

Page

Foreword.....	iv
Introduction.....	v
<b>1 Scope.....</b>	<b>1</b>
<b>2 Normative references.....</b>	<b>1</b>
<b>3 Terms and definitions.....</b>	<b>1</b>
<b>4 Principle.....</b>	<b>3</b>
<b>5 Reagent.....</b>	<b>4</b>
<b>6 Apparatus.....</b>	<b>4</b>
6.1 Volumetric glassware.....	4
6.2 Inductively coupled plasma atomic emission spectrometer.....	4
6.2.1 General.....	4
6.2.2 Line spectra selection.....	4
<b>7 Procedure.....</b>	<b>5</b>
7.1 Weighing the test portion.....	5
7.2 Sample preparation.....	6
7.3 Preparation of calibration solutions.....	6
7.4 Measurements.....	7
7.4.1 Instrument set-up.....	7
7.4.2 Measurement of the calibration solution and calibration curve construction.....	7
7.4.3 Measurement of the test solution.....	7
<b>8 Calculation and expression of results.....</b>	<b>7</b>
8.1 Method of calculation.....	7
8.2 Precision.....	8
8.2.1 Interlaboratory test.....	8
8.2.2 Statistical analysis.....	8
<b>9 Test report.....</b>	<b>8</b>
<b>Annex A (informative) Interlaboratory test results.....</b>	<b>9</b>
<b>Annex B (informative) Regression formulae of precision.....</b>	<b>10</b>
<b>Bibliography.....</b>	<b>11</b>