

# DIN EN 14977:2006-09 (E)

## Copper and copper alloys - Detection of tensile stress - 5 % ammonia test

---

<b>Contents</b>		<b>Page</b>
Foreword .....		3
Introduction .....		4
1 <b>Scope</b> .....		5
2 <b>Principle</b> .....		5
3 <b>Terms and definitions</b> .....		5
4 <b>Test solution</b> .....		5
5 <b>Test pieces</b> .....		6
6 <b>Procedure</b> .....		6
7 <b>Test requirements</b> .....		6
8 <b>Test report</b> .....		6
Bibliography .....		7