

DIN EN 14977:2006-09 (E)

Copper and copper alloys - Detection of tensile stress - 5 % ammonia test

Contents		Page
	Foreword	3
	Introduction	4
1	Scope	5
2	Principle	5
3	Terms and definitions	5
4	Test solution	5
5	Test pieces	6
6	Procedure	6
7	Test requirements	6
8	Test report	6
	Bibliography	7