

DIN EN 16729-5:2023-07 (E)

Railway applications - Infrastructure - Non-destructive testing on rails in track - Part 5: Non-destructive testing on welds in track

Contents		Page
European foreword		4
Introduction		5
1	Scope	6
2	Normative references	6
3	Terms and definitions	6
4	Symbols and abbreviations	6
5	NDT methods to detect defects in rail welds	7
5.1	General	7
5.2	Visual testing - VT	9
5.2.1	General	9
5.2.2	VT inspection zone	9
5.2.3	Example of defects	9
5.3	Ultrasonic Testing -- UT	9
5.3.1	General	9
5.3.2	UT inspection zone	9
5.3.3	Example of defects	9
6	Description of weld defects	10
6.1	Defects in electric arc repair welds	10
6.1.1	Volumetric defects - Porosity	10
6.1.2	Planar defects	11
6.2	Defects in flash butt welds (Tri-metallic welds)	15
6.3	Defects in aluminothermic weld	17
6.3.1	Volumetric defects	17
6.3.2	Planar defects	23
6.3.3	Thermal contraction (Hot Tear)	27
6.3.4	Fatigue cracks	28
7	Documentation	30
7.1	General	30
7.2	Requirements of documentation VT	30
7.3	Requirements of documentation UT	30
Annex A (informative) Visual testing procedures on welds		31
A.1	General	31
A.2	Visual testing on welds	31
A.2.1	Testing equipment	31
A.2.2	Testing preparation and procedure	31
Annex B (informative) Ultrasonic testing procedures on welds		32
B.1	General	32
B.2	Ultrasonic testing on welds	32
B.2.1	Testing equipment	32

B.2.2	Testing preparation and procedures	39
B.3	Phase W: Walking stick	39
B.3.1	General	39
B.3.2	Overview	39
B.3.3	Reference block for inspection W.1	39
B.3.4	Reference block for inspections W.2 and W.3	39
B.3.5	Transfer correction applied to inspections W.1 to W.3	40
B.3.6	Couplant	40
B.3.7	Inspection zone	40
B.4	Phase H: Single probes	40
B.4.1	General	40
B.4.2	Overview	40
B.4.3	Reference block for inspection H.1	40
B.4.4	Reference block for inspection H.2	41
B.4.5	Reference block for inspections H.3 and H.4	41
B.4.6	Transfer correction applied to inspections H.1 to H.4	41
B.4.7	Couplant	44
B.4.8	Inspection zones	44
B.5	Phase T: Tandem 45° on the running surface	48
B.5.1	Overview	48
B.5.2	Reference block for inspection T.1	48
B.5.3	Transfer correction applied to inspection T.1	48
B.5.4	Couplant	48
B.5.5	Inspection zone for T.1	48
B.6	Phase TS: Tandem 70° on the side of the rail head, web and foot	49
B.6.1	Overview	49
B.6.2	Reference block for inspection TS.1	50
B.6.3	Reference block for inspection TS.2	51
B.6.4	Reference block for inspection TS.3	52
B.6.5	Transfer correction applied to inspections TS.1 to TS.3	52
B.6.6	Couplant	53
B.6.7	Inspection zones	53
Bibliography		55