

DIN EN ISO 6789-1:2017-07 (E)

Assembly tools for screws and nuts - Hand torque tools - Part 1: Requirements and methods for design conformance testing and quality conformance testing: minimum requirements for declaration of conformance (ISO 6789-1:2017)

| Contents | Page |
|--|-------------|
| European foreword | 3 |
| Foreword | 4 |
| Introduction | 5 |
| 1 Scope | 6 |
| 2 Normative references | 6 |
| 3 Terms, definitions and symbols | 6 |
| 3.1 Terms and definitions | 6 |
| 3.2 Symbols, designations and units | 8 |
| 4 Classification | 8 |
| 5 Requirements | 8 |
| 5.1 Design conformance testing | 8 |
| 5.1.1 General | 8 |
| 5.1.2 Maximum torque values | 9 |
| 5.1.3 Specified torque range | 9 |
| 5.1.4 Scales, dials and displays | 9 |
| 5.1.5 Maximum permissible deviation | 10 |
| 5.1.6 Overloading test | 10 |
| 5.1.7 Endurance test | 10 |
| 5.1.8 Effect of geometric changes | 11 |
| 5.2 Quality conformance testing | 12 |
| 5.3 Conformance test during use | 12 |
| 6 Torque measurement | 12 |
| 6.1 Torque measurement system | 12 |
| 6.2 Application of torque | 13 |
| 6.3 Ambient conditions | 13 |
| 6.4 Measurement requirements | 14 |
| 6.5 Measurement sequence | 16 |
| 6.5.1 General | 16 |
| 6.5.2 Indicating torque tools, Type I | 16 |
| 6.5.3 Setting torque tools, Type II | 16 |
| 7 Calculation of deviation | 17 |
| 7.1 General | 17 |
| 7.2 Calculation example 1 | 17 |
| 7.3 Calculation example 2 | 18 |
| 8 Declaration of conformance | 19 |
| 9 Marking | 19 |
| Annex A (normative) Examples of indicating torque tools (Type I) | 21 |
| Annex B (normative) Examples of setting torque tools (Type II) | 22 |
| Annex C (informative) Measurement sequence flowchart for torque tools | 24 |
| Bibliography | 27 |