

# DIN ISO 8764-1:2006-01 (E)

## Assembly tools for screws and nuts - Screwdrivers for cross-recessed head screws - Part 1: Driver tips (ISO 8764-1:2004)

---

<b>Contents</b>		<b>Page</b>
Foreword .....		2
1	<b>Scope .....</b>	<b>3</b>
2	<b>Normative references .....</b>	<b>3</b>
3	<b>Shapes and dimensions .....</b>	<b>3</b>
4	<b>Technical requirements .....</b>	<b>7</b>
5	<b>Inspection of dimensions .....</b>	<b>7</b>
6	<b>Torque test .....</b>	<b>11</b>
7	<b>Designation .....</b>	<b>14</b>
<b>Annex A (informative) Explanation of choice of gauge dimensions for form PH tips .....</b>		<b>15</b>
<b>Annex B (informative) Guide for inspection gauges for form PZ tips .....</b>		<b>16</b>