

DIN EN 15841:2010-04 (E)

Ambient air quality - Standard method for determination of arsenic, cadmium, lead and nickel in atmospheric deposition

Contents		Page
Foreword		3
1	Scope	4
2	Normative references	4
3	Terms, definitions and abbreviations	5
4	Principle	7
5	Apparatus and reagents	8
6	Sampling	11
7	Sample preparation	12
8	Quality control	14
9	Calculation of results	14
10	Performance characteristics determined in lab and field tests	17
11	Reporting of results	20
Annex A (informative) Standard operating procedures for sampling		22
Annex B (informative) Estimation of the measurement uncertainty of the method		26
Annex C (informative) Uncertainty budget		30
Annex ZA (informative) Relationship between this European Standard and the essential requirements of EU Directives		31
Bibliography		32