

DIN EN 15841:2010-04 (E)

Ambient air quality - Standard method for determination of arsenic, cadmium, lead and nickel in atmospheric deposition

Contents		Page
Foreword		3
1 Scope		4
2 Normative references		4
3 Terms, definitions and abbreviations		5
4 Principle		7
5 Apparatus and reagents		8
6 Sampling		11
7 Sample preparation		12
8 Quality control		14
9 Calculation of results		14
10 Performance characteristics determined in lab and field tests		17
11 Reporting of results		20
Annex A (informative) Standard operating procedures for sampling		22
Annex B (informative) Estimation of the measurement uncertainty of the method		26
Annex C (informative) Uncertainty budget		30
Annex ZA (informative) Relationship between this European Standard and the essential requirements of EU Directives		31
Bibliography		32