

DIN EN 13284-2:2018-02 (E)

Stationary source emissions - Determination of low range mass concentration of dust - Part 2 : Quality assurance of automated measuring systems

	Contents	Page
European foreword	4	
Introduction	5	
1 Scope	6	
2 Normative references	6	
3 Terms and definitions	6	
4 Symbols and abbreviations	6	
4.1 Symbols	6	
4.2 Abbreviations	7	
5 Principle	8	
6 Calibration and validation of the AMS (QAL2)	8	
6.1 General	8	
6.2 Functional test	8	
6.3 Parallel measurements with the SRM	8	
6.3.1 General	8	
6.3.2 Increasing the dust concentration	9	
6.3.3 SRM measured values below the limit of quantification	9	
6.3.4 Semi-volatiles	9	
6.4 Data evaluation	10	
6.4.1 Preparation of data	10	
6.4.2 Selection of data points from automated SRM	10	
6.4.3 Establishing the calibration function	10	
6.5 Calibration function of the AMS and its validity	11	
6.6 Calculation of variability	11	
6.7 Test of variability	11	
6.8 QAL2 report	11	
7 Ongoing quality assurance during operation (QAL3)	11	
8 Annual Surveillance Test (AST)	11	
9 Documentation	12	
Annex A (informative) Example of calculation of the calibration function and of the variability test ..	13	
A.1 General	13	
A.2 Data evaluation	13	
A.2.1 General	13	
A.2.2 Calculation of measured values of the SRM at standard conditions	15	
A.2.3 Calibration function	16	
A.2.4 Calibrated AMS measured values	17	
A.2.5 Conversion of data to standard conditions	18	
A.2.6 Valid calibration range	18	
A.2.7 Test of variability	19	

Annex B (informative) Configuration of extractive dust measuring systems	22
B.1 General	22
B.2 Isokinetic sampling	22
B.3 Calibration function	23
Annex C (informative) Number of parallel measurements for calibration	24
C.1 General	24
C.2 Errors in calibration at low dust concentration	24
Annex D (informative) Extension of the calibration range by changing the dust concentration	25
D.1 General	25
D.2 Changing plant load	25
D.3 Changing operation of dust arrestment plant	25
D.4 Injection of dust	26
Annex E (informative) Quadratic regression	28
Annex F (informative) Configuration of AMS at mass concentration below the limit of quantification of the SRM	30
F.1 General	30
F.2 Techniques directly dealing with mass	30
F.3 Scattered-light measuring systems	30
F.4 Surrogate generators	30
F.5 Missing alternative calibration techniques	30
Annex G (informative) Significant technical changes	32
Bibliography	33