

# DIN EN 13284-2:2018-02 (E)

## Stationary source emissions - Determination of low range mass concentration of dust - Part 2 : Quality assurance of automated measuring systems

---

<b>Contents</b>		<b>Page</b>
European foreword .....		4
Introduction .....		5
1	Scope .....	6
2	Normative references .....	6
3	Terms and definitions .....	6
4	Symbols and abbreviations .....	6
4.1	Symbols .....	6
4.2	Abbreviations .....	7
5	Principle .....	8
6	Calibration and validation of the AMS (QAL2) .....	8
6.1	General .....	8
6.2	Functional test .....	8
6.3	Parallel measurements with the SRM .....	8
6.3.1	General .....	8
6.3.2	Increasing the dust concentration .....	9
6.3.3	SRM measured values below the limit of quantification .....	9
6.3.4	Semi-volatiles .....	9
6.4	Data evaluation .....	10
6.4.1	Preparation of data .....	10
6.4.2	Selection of data points from automated SRM .....	10
6.4.3	Establishing the calibration function .....	10
6.5	Calibration function of the AMS and its validity .....	11
6.6	Calculation of variability .....	11
6.7	Test of variability .....	11
6.8	QAL2 report .....	11
7	Ongoing quality assurance during operation (QAL3) .....	11
8	Annual Surveillance Test (AST) .....	11
9	Documentation .....	12
Annex A (informative) Example of calculation of the calibration function and of the variability test ..		13
A.1	General .....	13
A.2	Data evaluation .....	13
A.2.1	General .....	13
A.2.2	Calculation of measured values of the SRM at standard conditions .....	15
A.2.3	Calibration function .....	16
A.2.4	Calibrated AMS measured values .....	17
A.2.5	Conversion of data to standard conditions .....	18
A.2.6	Valid calibration range .....	18
A.2.7	Test of variability .....	19

<b>Annex B (informative) Configuration of extractive dust measuring systems .....</b>	<b>22</b>
<b>B.1 General .....</b>	<b>22</b>
<b>B.2 Isokinetic sampling .....</b>	<b>22</b>
<b>B.3 Calibration function .....</b>	<b>23</b>
<b>Annex C (informative) Number of parallel measurements for calibration .....</b>	<b>24</b>
<b>C.1 General .....</b>	<b>24</b>
<b>C.2 Errors in calibration at low dust concentration .....</b>	<b>24</b>
<b>Annex D (informative) Extension of the calibration range by changing the dust concentration .....</b>	<b>25</b>
<b>D.1 General .....</b>	<b>25</b>
<b>D.2 Changing plant load .....</b>	<b>25</b>
<b>D.3 Changing operation of dust arrestment plant .....</b>	<b>25</b>
<b>D.4 Injection of dust .....</b>	<b>26</b>
<b>Annex E (informative) Quadratic regression .....</b>	<b>28</b>
<b>Annex F (informative) Configuration of AMS at mass concentration below the limit of quantification of the SRM .....</b>	<b>30</b>
<b>F.1 General .....</b>	<b>30</b>
<b>F.2 Techniques directly dealing with mass .....</b>	<b>30</b>
<b>F.3 Scattered-light measuring systems .....</b>	<b>30</b>
<b>F.4 Surrogate generators .....</b>	<b>30</b>
<b>F.5 Missing alternative calibration techniques .....</b>	<b>30</b>
<b>Annex G (informative) Significant technical changes .....</b>	<b>32</b>
<b>Bibliography .....</b>	<b>33</b>