

# ISO 20181:2023-02 (E)

## Stationary source emissions - Quality assurance of automated measuring systems

---

<b>Contents</b>		<b>Page</b>
Foreword .....		v
Introduction .....		vi
1	Scope .....	1
2	Normative references .....	1
3	Terms and definitions .....	1
4	Symbols and abbreviated terms .....	6
4.1	Symbols .....	6
4.2	Abbreviated terms .....	7
5	Principle .....	7
5.1	General .....	7
5.2	Limitations .....	9
5.3	Measurement site and installation .....	9
5.4	Testing laboratories performing SRM measurements .....	10
6	Calibration and validation of the AMS (QAL2) .....	10
6.1	General .....	10
6.2	Functional test .....	11
6.3	Parallel measurements with the SRM .....	12
6.4	Data evaluation .....	14
6.4.1	Preparation of data .....	14
6.4.2	Selection of data points from automated SRM .....	15
6.4.3	Establishing the calibration function .....	15
6.5	Calibration function of the AMS and its validity .....	16
6.6	Calculation of variability .....	18
6.7	Test of variability .....	19
6.8	QAL2 report .....	19
7	Ongoing quality assurance during operation (QAL3) .....	20
7.1	General .....	20
7.2	Procedures to maintain ongoing quality .....	21
7.3	Choosing control charts .....	21
7.4	Control chart limits .....	22
7.4.1	General .....	22
7.4.2	Calculation of control chart limits using performance data .....	22
7.4.3	Calculation of control chart limits using the maximum permissible uncertainty .....	23
7.5	Zero and span measurements .....	23
7.5.1	General .....	23
7.5.2	Frequency of zero and span measurements .....	23
7.5.3	Extractive gas analysis systems .....	24
7.5.4	In-situ gas-monitoring AMS .....	24
7.5.5	Particulate-monitoring AMS .....	25
7.6	Documentation of control charts .....	25
8	Annual surveillance test (AST) .....	25
8.1	General .....	25
8.2	Functional test .....	26

8.3	Parallel measurements with the SRM .....	26
8.4	Data evaluation .....	27
8.5	Calculation of variability .....	28
8.6	Test of variability and validity of the calibration function .....	28
8.7	AST report .....	29
9	Documentation .....	29
Annex A (normative) QAL2 and AST functional test of AMS .....		30
Annex B (normative) Test of linearity .....		34
Annex C (informative) Control charts .....		36
Annex D (normative) Documentation .....		46
Annex E (informative) Examples of calculation of the calibration function and of the variability test		48
Annex F (informative) Example of calculation of the standard deviation $s_{AMS}$ of the AMS at zero and span level .....		63
Annex G (informative) Example of using the calibration function and testing the variability and validity of the calibration function in the AST .....		66
Annex H (informative) Implementation of QAL1 .....		70
Annex I (normative) $k_v$ and $t_{0,95}$ ; N-1 values .....		71
Annex J (informative) Significant technical changes .....		72
Bibliography .....		74