

# DIN EN 12341:2023-10 (E)

Ambient air - Standard gravimetric measurement method for the determination of the PM<(Index)10> or PM<(Index)2,5> mass concentration of suspended particulate matter

---

<b>Contents</b>	<b>Page</b>
European foreword .....	4
1 Scope.....	6
2 Normative references.....	6
3 Terms, definitions, symbols and abbreviations .....	6
3.1 Terms and definitions.....	6
3.2 Symbols and abbreviations .....	10
4 Principle .....	12
4.1 Description of the standard measuring principle.....	12
4.2 Initial use and procedures for ongoing QA/QC.....	12
4.3 Evaluation of measurement uncertainty.....	12
5 Equipment, facilities and testing.....	12
5.1 Sampling system components and programme for type testing .....	12
5.1.1 General.....	12
5.1.2 Sampler design .....	16
5.1.3 Standard inlet design.....	16
5.1.4 Connecting pipe work .....	17
5.1.5 Filter holder and filter .....	17
5.1.6 Flow control system.....	18
5.1.7 Temperature sensors .....	20
5.1.8 Ambient pressure sensor.....	20
5.1.9 Sampling period .....	20
5.1.10 Leak tightness of the sampling system .....	20
5.1.11 Storage conditions.....	22
5.1.12 Recording of operational parameters.....	22
5.1.13 Effect of failure of mains power .....	23
5.1.14 Effect of ending sampling early due to filter clogging .....	23
5.1.15 Firmware, software and manual versions .....	23
5.2 Sampling system components and programme for type testing .....	24
5.3 Field tests for type testing .....	25
5.3.1 General.....	25
5.3.2 Performance tests.....	25
5.4 Type testing report.....	26
6 Filter conditioning, sampling, weighing facilities and weighing procedures .....	26
6.1 General.....	26
6.2 Weighing Facilities .....	28
6.2.1 Weighing room .....	28
6.2.2 Balance .....	28
6.3 Filter conditioning and weighing prior to sampling .....	28
6.4 Sampling procedure.....	29
6.4.1 Filter cassette loading.....	29
6.4.2 Filter sampling.....	29
6.4.3 Sample storage and transport procedures.....	29
6.5 Filter conditioning and weighing after sampling.....	29
6.6 Weighing room procedures .....	30
6.7 Filter blanks for ongoing quality control .....	30
6.7.1 General.....	30

6.7.2	Weighing room blanks.....	30
6.7.3	Field blanks.....	31
7	Ongoing quality control.....	31
7.1	General .....	31
7.2	Frequency of calibrations, checks and maintenance.....	31
7.3	Recording of operational parameters.....	32
7.4	Maintenance of the sampling system .....	33
7.5	Checks of sampler sensors .....	33
7.6	Calibration of sampler sensors.....	33
7.7	Checks of the sampler flow rate .....	34
7.8	Calibration of the sampler flow rate.....	34
7.9	Leak check of the sampling system .....	34
7.10	Checks of weighing facility sensors.....	34
7.11	Calibration of weighing facility sensors .....	34
7.12	Balance .....	34
7.13	Check of the accuracy of sampler clock .....	35
8	Expression of results .....	35
9	Performance characteristics of the method .....	35
9.1	General .....	35
9.2	GUM concept.....	35
9.3	Individual uncertainty sources .....	37
9.3.1	General .....	37
9.3.2	Collected particulate mass .....	37
9.3.3	Time (t).....	40
9.3.4	Uncertainty budget .....	40
9.4	Expanded uncertainty vs. EU Data Quality Objectives .....	42
Annex A	(normative) Design drawing of standard inlet for the sampling of PM <sub>10</sub> and PM <sub>2,5</sub> ....	43
Annex B	(informative) Scheme of PM standard sampler.....	44
Annex C	(informative) Suitability tests for filters .....	45
Annex D	(normative) Initial suitability testing of weighing facilities .....	47
Annex E	(informative) Results of experimental work.....	48
Annex F	(informative) Impactor efficiency .....	50
Annex G	(normative) Elements of type testing report.....	52
Annex H	(informative) Example for uncertainty budget calculation .....	54
Annex I	(informative) Technical changes in EN 12341 with respect to version 2014 [21] .....	58
Bibliography	.....	59